



**ACHTUNG !!!**  
Pos. 18 und 19 müssen  
gemeinsam getauscht werden!

**CAUTION !!!**  
Pos. 18 and 19 have to be  
changed together!

# ENTHALTEN IM DICHTSATZ MOTOR LC4  
INCLUDED IN GASKET-SET ENGINE LC4

Pos	Part Number	Description	Additional Text	Quantity
1	0025050256	HH COLLAR SCREW M5X25 ISA30		4.00
2	75032006000	SPRING RING 07		4.00
3	58532080000	CLUTCHSPRING 3,0X33,5		4.00
4	75032003000	PRESSURE CAP		1.00
5	60036073050	HEXAGON NUT M20X1,5 7MM		1.00
6	47032020000	thrust washer 20x32x2		1.00
7	75032002002	INNER CLUTCH HUB MOVABLE		1.00
8	75032033000	CLUTCH RELEASE SPRING		4.00
9	75032002001	INNER CLUTCH HUB FIXED		1.00

10	75032009000	STEPPED WASHER 07		1.00
11	75032007000	HALF-WASHER 07		2.00
12	75032001044	OUTER CLUTCH HUB CPL.		1.00
14	75032050001	OIL PUMP DRIVE WHEEL 07		1.00
15	56532095000	NEEDLE BEARING K26X30X22ZW.KSE		1.00
16	75032017000	WASHER 26X40X2 07		1.00
17	0625060016	deep groove ball bearing 6001.		1.00
18	75032055100	PRESSURE BOLT 08		1.00
19	75032054200	PUSH ROD 08		1.00
20	59032065000	GASKET FOR SLAVE CYLINDER		1.00
21	0770300015	O-ring 30x1.5 NBR 70		1.00
23	54732064000	BLEEDER SCREW WITH CAP		1.00
24	75032061044	OUTPUT CYL. WITH BLEEDER SCREW		1.00
26	0025060356	HH collar screw M6x35 TX30		1.00
27	0025060206	HH collar screw M6x20 TX30		2.00
28	75032112000	STEEL DISK 1,5 MM LC4 '07		6.00
29	58332011300	LINING DISK 2,7MM FCC 02		7.00
30	58632016000	RONDELLA ANTIVIBRAZIONE SET		1.00
31	75032111100	LINING DISC CUT OUT		1.00
32	75032112100	STEEL DISK 1,5MM NITRIDED		1.00
33	75032032000	HOLDING SCREW GMB-M5X35		2.00
99	75032011110	CLUTCH KIT 690/701		1.00