



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|---------------|--------------------------------|-----------------|----------|
| 1 | 96234005033 | assembly lever gear shift | | 1.00 |
| 2 | 90234039000 | SPRING SHIFT RAIL | | 2.00 |
| 3 | J440001301500 | Bush | | 1.00 |
| 4 | 96034014000 | spring torsion | | 1.00 |
| 5 | J690001315000 | washer plain-id 13xod 28xthk 1 | | 1.00 |
| 6 | 90134016000 | SPRING GUIDE | | 1.00 |
| 7 | 96034031010 | linkage gear shift lever | | 1.00 |
| 8 | J900000602200 | BOLT FLANGED M6X1 | | 1.00 |
| 9 | 96334036033 | shifting rod assembly | | 1.00 |
| 10 | 96334031033 | gear lever assembly | | 1.00 |
| 11 | J625060800 | BEARING CHANGE LEVER | | 2.00 |
| 12 | 90134035000 | GEAR SHIFT LEVER RUBBER | | 1.00 |
| 14 | J520000700100 | Spring Tension | | 1.00 |

| | | | | |
|----|---------------|--------------------------------|-------|------|
| 15 | 90534034300 | BOLT SHIFT LEVER | black | 1.00 |
| 16 | 96234001001 | fork gear shift output 1 | | 1.00 |
| 17 | 90234019000 | SHIFT RAIL | | 1.00 |
| 18 | 96234001000 | fork gear shift input | | 1.00 |
| 19 | 90130001001 | SOCKET HEAD SCREW M6X20 | | 1.00 |
| 20 | 96034015000 | guide gear shift | | 1.00 |
| 21 | J940000400800 | Cylinder pin 4x8 | | 1.00 |
| 22 | 90134012002 | SPACER | | 1.00 |
| 23 | 96234012000 | drum gear shift | | 1.00 |
| 24 | 93003044000 | cover dust tie rod | | 2.00 |
| 26 | J900000601804 | bolt socket-M6x1xl 14xprecoat | | 1.00 |
| 27 | J690001013500 | washer plain-id10xod18.5xthk1. | | 1.00 |
| 28 | 96234013033 | stopper assembly drum | | 1.00 |
| 29 | J125061416 | Washer, 6x14x1.2 | | 1.00 |
| 30 | 96034023000 | spring torsion | | 1.00 |
| 31 | 93834020000 | Gear shift rail | | 1.00 |
| 32 | 90534031020 | WASHER SHIFTING LEVER | | 2.00 |
| 33 | 96234001002 | fork gear shift output 2 | | 1.00 |