



| Pos | Part Number   | Description                | Additional Text | Quantity |
|-----|---------------|----------------------------|-----------------|----------|
| 1   | 96211075000   | harness wiring             |                 | 1.00     |
| 2   | J900000602800 | SK-Bundschraube M6x28      |                 | 2.00     |
| 3   | A60111034000  | UNIT REGULATOR             |                 | 1.00     |
| 4   | J025080123    | HH COLLAR SCREW M8X12 SW12 |                 | 1.00     |
| 5   | 96311060000   | Horn                       |                 | 1.00     |
| 6   | 96311061000   | Bracket horn               |                 | 1.00     |
| 7   | 28111096000   | Transil unit               |                 | 1.00     |
| 9   | 90508006001   | SOCKET HEAD BOLT M6X12     |                 | 2.00     |
| 11  | 96311083000   | Connector support          |                 | 1.00     |

|    |               |                                 |  |      |
|----|---------------|---------------------------------|--|------|
| 12 | 96314086000   | UNIT CONNECTIVITY               |  | 1.00 |
| 13 | 96241088050   | BRACKET SENSOR ROLL OVER        |  | 1.00 |
| 14 | J650001801400 | grommet                         |  | 3.00 |
| 15 | J690000410000 | washer plain                    |  | 2.00 |
| 17 | J900000401600 | screw tapping pan cross dia 4.  |  | 4.00 |
| 18 | A60111058000  | RELAY STARTER                   |  | 1.00 |
| 19 | 93311058000   | Rubber damper starter relay     |  | 1.00 |
| 20 | 90611057000   | relay (interlock)               |  | 5.00 |
| 21 | 93511088000   | Fuse 10a                        |  | 9.00 |
| 21 | 90111088015   | Fuse 15A                        |  | 5.00 |
| 21 | 90111088030   | Fuse 30A                        |  | 1.00 |
| 21 | 90111088020   | Fuse 20A                        |  | 2.00 |
| 22 | 96311097000   | CABLE EARTH                     |  | 1.00 |
| 23 | 96311007000   | CABLE PUMP FUEL                 |  | 1.00 |
| 24 | 96338091100   | CABLE SWITCH PRESSURE OIL       |  | 1.00 |
| 25 | 93811099000   | wiring harness temperatur sens  |  | 1.00 |
| 26 | 96311059000   | Starter cable                   |  | 1.00 |
| 29 | 93541088000   | rollover sensor                 |  | 1.00 |
| 31 | 96311041000   | socket charger USB              |  | 1.00 |
| 32 | J025060122    | Hex collar screw M6X12          |  | 2.00 |
| 33 | 93803001022   | Cable tie                       |  | 3.00 |
| 34 | 96311058010   | cap relay starter               |  | 1.00 |
| 35 | 96311097002   | Busbar plate                    |  | 1.00 |
| 36 | J797060003    | TOOTHED WASHER M6               |  | 3.00 |
| 37 | J797100006    | washer toothed internal         |  | 1.00 |
| 38 | J700000202000 | PIN SNAP                        |  | 1.00 |
| 39 | J800000601000 | collar number plate mounting    |  | 1.00 |
| 40 | J920000601800 | PIN                             |  | 1.00 |
| 99 | 96311081000   | Rear turn signal wiring harness |  | 1.00 |
| 99 | 96311093000   | wiring harness BCCU             |  | 1.00 |
| 99 | 96311098000   | CABLE EARTH                     |  | 1.00 |