



Pos	Part Number	Description	Additional Text	Quantity
1*	0625062062	BALL BEARING 6206 C3 J1 NSK		1.00
2*	0405263113	NEEDLE BEAR. K 26-31-13		1.00
3*	60233005000	IDLER GEAR 5.G		1.00
4*	61233042000	STOP DISK 27,9/35,75/1,5		1.00
5*	60233050000	COPPER WASHER 25,5		1.00
6*	60233003000	SLIDING GEAR 3/4 TH G .		1.00
7*	61233041000	STOP DISK 22,2/30,2/1,5		1.00
8*	0405222613	NEEDLE BEAR. K 22X26X13 TN		1.00
9*	60233006000	IDLER GEAR 6.G		1.00
10*	60233002000	SOLID GEAR 2.G		1.00
11*	60033040015	STOP DISK 20,2X28X1,5		0.00
11*	60033040016	STOP DISK 20,2/28/1,6		0.00
11*	60033040017	STOP DISK 20,2/28/1,7		0.00
11*	60033040018	STOP DISK 20,2/28/1,8		0.00
11*	60033040019	STOP DISK 20,2/28/1,9		0.00
11*	60033040020	STOP DISK 20,2/28/2,0		0.00
11*	60033040021	STOP DISK 20,2/28/2,1		0.00
11*	60033040022	STOP DISK 20,2/28/2,2		0.00
11*	60033040010	STOP DISK 20,2X28X1,0		0.00
11*	60033040011	STOP DISK 20,2X28X1,1		0.00
11*	60033040012	STOP DISK 20,2X28X1,2		0.00
11*	60033040013	STOP DISK 20,2X28X1,3		0.00
11*	60033040014	STOP DISK 20,2X28X1,4		0.00
12*	60233001000	MAIN SHAFT 12-T.		1.00
13*	0618091312	NEEDLE BUSH HK0912 9/13/12 03		1.00
14*	0625062040	BALL BEARING 6204 DU J1 C3		1.00

* = New part