




| Pos | Part Number | Description                   | Additional Text | Quantity |
|-----|-------------|-------------------------------|-----------------|----------|
| 1*  | 0625062062  | BALL BEARING 6206 C3 J1 NSK   |                 | 1.00     |
| 2*  | 0405263113  | NEEDLE BEAR. K 26-31-13       |                 | 1.00     |
| 3*  | 60233005000 | IDLER GEAR 5.G                |                 | 1.00     |
| 4*  | 61233042000 | STOP DISK 27,9/35,75/1,5      |                 | 1.00     |
| 5*  | 60233050000 | COPPER WASHER 25,5            |                 | 1.00     |
| 6*  | 60233003000 | SLIDING GEAR 3/4 TH G .       |                 | 1.00     |
| 7*  | 61233041000 | STOP DISK 22,2/30,2/1,5       |                 | 1.00     |
| 8*  | 0405222613  | NEEDLE BEAR. K 22X26X13 TN    |                 | 1.00     |
| 9*  | 60233006000 | IDLER GEAR 6.G                |                 | 1.00     |
| 10* | 60233002000 | SOLID GEAR 2.G                |                 | 1.00     |
| 11* | 60033040015 | STOP DISK 20,2X28X1,5         |                 | 0.00     |
| 11* | 60033040016 | STOP DISK 20,2/28/1,6         |                 | 0.00     |
| 11* | 60033040017 | STOP DISK 20,2/28/1,7         |                 | 0.00     |
| 11* | 60033040018 | STOP DISK 20,2/28/1,8         |                 | 0.00     |
| 11* | 60033040019 | STOP DISK 20,2/28/1,9         |                 | 0.00     |
| 11* | 60033040020 | STOP DISK 20,2/28/2,0         |                 | 0.00     |
| 11* | 60033040021 | STOP DISK 20,2/28/2,1         |                 | 0.00     |
| 11* | 60033040022 | STOP DISK 20,2/28/2,2         |                 | 0.00     |
| 11* | 60033040010 | STOP DISK 20,2X28X1,0         |                 | 0.00     |
| 11* | 60033040011 | STOP DISK 20,2X28X1,1         |                 | 0.00     |
| 11* | 60033040012 | STOP DISK 20,2X28X1,2         |                 | 0.00     |
| 11* | 60033040013 | STOP DISK 20,2X28X1,3         |                 | 0.00     |
| 11* | 60033040014 | STOP DISK 20,2X28X1,4         |                 | 0.00     |
| 12* | 60233001000 | MAIN SHAFT 12-T.              |                 | 1.00     |
| 13* | 0618091312  | NEEDLE BUSH HK0912 9/13/12 03 |                 | 1.00     |
| 14* | 0625062040  | BALL BEARING 6204 DU J1 C3    |                 | 1.00     |

\* = New part