



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|-------------|---------------------------------|-----------------------|----------|
| 1 | 12187E08 | Shock absorber 990 ADVENTURE | | 1.00 |
| 2 | 50180412S1 | Shock absorber upper part compl | | 1.00 |
| 3 | 50180358S3 | Shock absorber lower part compl | | 1.00 |
| 4 | 60004016000 | SCREW M14X1,5 L=55MM 03 | | 1.00 |
| 5 | 60004017000 | SCREW M14X1,5 L=73MM 03 | | 1.00 |
| 11 | 50180366 | Bearing bush 14x15/18/24,5x10, | | 2.00 |
| 12 | R12012 | Ball joint bearing kit top 12m | | 1.00 |
| 13 | R12013 | REP.KIT BEAR/SEAL LOWER ADV 07 | | 1.00 |
| 15 | 50180365 | Bearing bush 14x16/21,8/29x14 | | 2.00 |
| 21 | 50180095 | HS cylinder-head screw R1/8 I8 | | 1.00 |
| 30 | 50180213S4 | | SX | 1.00 |
| 41 | 50180133 | spreader ring 50X1,5 | ONLY FOR STEEL-SPRING | 2.00 |
| 42 | 50180081 | Spring guide 54,15x60x40 | ONLY FOR STEEL-SPRING | 1.00 |

| | | | | |
|----|-------------|--------------------------------|------------|------|
| 43 | 50180114 | Intermediate washer spring 61, | Super Moto | 1.00 |
| 44 | 91210035SA | SPRING 140-225 (62) D=14,5 | | 0.00 |
| 44 | 91210036SA | SPRING 150-225 (62) D=14,5 | | 0.00 |
| 45 | 50180402 | Interm. ring spring ret. H=3.5 | | 1.00 |
| 46 | 50180352 | O-ring 66,27x1,78 Viton70 | | 1.00 |
| 48 | 50180273 | Round-wire snap ring 58,5x2 | | 1.00 |
| 51 | 46811208 | Rubber cap do not open 22x5,5 | | 1.00 |
| 52 | 36120151 | HS lock screw M5x6 | | 1.00 |
| 53 | 46810893 | O-ring 5,28x1,78 NBR70 black | | 1.00 |
| 55 | 50180276 | Rubber pad 17,2x45,2x40 black | | 1.00 |
| 56 | 50180165 | Cap 50,1x17,5 h6 | | 1.00 |
| 62 | 50180434S | ADJUSTING SCREW REBOUND TRAVEL | | 1.00 |
| 97 | 00050000035 | MONOSHOCK REP. KIT | | 0.00 |
| 98 | 50180751S1 | SHOCK ABSORBER FLUID 5 LT | | 1.00 |
| 99 | R12008 | REPAIR-KIT GASKET 5018 PDS 03 | | 1.00 |