



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|-------------|--------------------------------|-----------------|----------|
| 1 | 48600685S2 | AXLE CLAMP R/S CPL. 07 | | 1.00 |
| 2 | 48600686S2 | AXLE CLAMP L/S CPL. 07 | | 1.00 |
| 3 | 91410038S | SPRING C=9 L=250 D=5,1 05 | | 0.00 |
| 3 | 91410039S | SPRING C=9,5 L=250 D=5,25 05 | | 1.00 |
| 4 | 48600460 | WASHER 32X42X2,5 | | 2.00 |
| 5 | 48600579 | SPACER ALU D42 X 85 | | 2.00 |
| 6 | 48600053 | Preload bush 26,5x42x1,5 | | 2.00 |
| 6 | 48600036 | Preload bush 42x26,5x2,5 | ONLY FOR 200 SX | 2.00 |
| 6 | 48600037 | Preload bush 26,5x42x5 | | 2.00 |
| 7 | 48600431S | PRE-LOAD ADJ. CPL. M51X1,5 05 | | 2.00 |
| 8 | 48600580S1 | CARTRIDGE CPL. 07 | | 2.00 |
| 9 | 48600362 | OUTER TUBE L=500 | | 2.00 |
| 10 | R14009 | REPAIR-KIT GASKET 4860 MXMA 05 | | 1.00 |
| 11 | 48601166S1 | Fork Fluid Viscosity 4.0 5L | | 1.00 |
| 12 | T511 | SILICONE GREASE F. DUST STRI | | 1.00 |
| 13 | 48600013 | Supportwasher 50x57,6x1,5 | | 2.00 |

| | | | | |
|----|----------|--------------------------------|--|------|
| 14 | 48600399 | Shaft seal SKF 48x57,8x9,5 bla | | 2.00 |
| 15 | 48600070 | Snap ring SB58x1,5 acc drawing | | 2.00 |
| 16 | 48600400 | DUST CAP D=48 58,4X11,8 | | 2.00 |
| 17 | 48600428 | DU-BUSH D47XD49X20DDL02 | | 2.00 |
| 18 | 48600236 | Guide bushing 48x51x12 | | 2.00 |
| 19 | 48600245 | SPACER 50,95X0,85X161,5 | | 2.00 |
| 20 | 48601009 | Guide bushing 48x52x12 | | 2.00 |