



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|----------------|--------------------------------|-----------------|----------|
| 1 | A46030018000 | Crankshaft cpl. | | 1.00 |
| 2 | A46030015044 | Connecting rod rebuild kit | | 1.00 |
| 3 | 0988324510 | THRUST WASHER 988ST 32X0,1 | | 0.00 |
| 3 | 0988324515 | THRUST WASHER 988ST 32X0,15 | | 0.00 |
| 3 | 0988324530 | THRUST WASHER 988ST 32X0,30 | | 0.00 |
| 4 | 77330082200 | BEARING NJ 206 ECP/HN3C4HVA624 | | 2.00 |
| 5 | 0888030037 | WOODRUFF KEY DIN6888-3X3,7 | | 1.00 |
| 6 | 0910001801000S | Nut M18x1.5 Precote | | 1.00 |
| 7 | 0910002700800S | Nut M27x1 Precote | | 1.00 |
| 8 | 0760405561 | SHAFT SEAL RING A 40X55X6 V. | | 1.00 |
| 9 | 77232022100 | Spacer, primary gear | | 1.00 |
| 10 | 79232023124 | gear primary drive | | 1.00 |
| 11 | 0019050121S | INT. TORX FLAT HEAD M5X12 T25 | | 4.00 |
| 12 | 75030085100 | Retaining bracket crankshaft b | | 4.00 |
| 13 | 79030274000 | CIRCLIP PISTON PIN | | 2.00 |
| 14 | 79130231044 | Piston ring set | | 1.00 |

| | | | | |
|----|-----------------|---------------------------|--|------|
| 40 | A46030007000 I | PISTON Gr. I CPL. MX 250 | | 0.00 |
| 40 | A46030007000 II | Piston Gr. II cpl. MX 250 | | 0.00 |
| 98 | 00050002319 | Crankshaft repair kit | | 0.00 |
| 99 | A46030007010 I | Piston kit Gr. I MX 250 | | 0.00 |
| 99 | A46030007010 II | Piston kit gr. II MX 250 | | 0.00 |